

Drain Pipe Road Surface repair – Looking at getting steel plates over road surface until Raynes (contractor) will be able to get to repairs in July – August time frame. Steel plates will add additional cost. Compact testing will be done also on the road surface during actual repair which adds another additional cost. Final costs are awaiting BOD approval.

Pool - The pool has been cleaned and re-filled. The pump is running, but has a small leak. He is going to check the leak today, and hopefully be able to repair it without a lot of trouble. He has three life guards (exchange students) that he can let us have, but we need to find a place for them to live for the summer. I have one lot owner who said that her place will be available July 1st. I am waiting for two other people to get back to me. We have to act fast on this, as he said that if we don't employ them quickly, they will go elsewhere. If you know anyone who can put them up until July 1st as a rental, PLEASE contact Park Manager.

Paving - The blacktop cracks/holes repairs have been made. The tar sealing is being done today.